

L 1 = less-than-one (1) or zero(0)

A = Sample not tested, too long in transit

EST = High colony density preventing accurate count

G = Greater than

O/G = Overgrown with coliform present

B = More than 200 background colonies / 100 ml

D = Sample not tested; no collection date given

T = Sample submitted exceeded 30 hours holding time

<u>Date</u>	<u>Location</u>	<u>Total</u>	<u>Ecoli</u>	<u>Notes</u>
December 13, 2017	Sample Station #2 Earl Street near the school	L1	L1	
	Sample Station # 3 Marble Bay Road @ Van Anda Ave	L1	L1	
	Sample Station # 4 Smelter Road, across from Bob Gordon's	L1	L1	
	Sample Station # 5 Sellentin Street @ Sturt Bay Road	L1	L1	
	Sample Station # 6 Wall Street Pumphouse	L1	L1	
	Sample Station # 7 Copper Queen Street @ Alladin	L1	L1	
	Sample Station # 8 Storage Tank	L1	L1	
	Lake	30.5	1	

<u>Date</u>	<u>Location</u>	<u>Total</u>	<u>Ecoli</u>	<u>Notes</u>
November 8, 2017	Sample Station #2 Earl Street near the school	L1	L1	
	Sample Station # 3 Marble Bay Road @ Van Anda Ave	L1	L1	
	Sample Station # 4 Smelter Road, across from Bob Gordon's	L1	L1	
	Sample Station # 5 Sellentin Street @ Sturt Bay Road	L1	L1	
	Sample Station # 6 Wall Street Pumphouse	L1	L1	
	Sample Station # 7 Copper Queen Street @ Alladin	L1	L1	
	Sample Station # 8 Storage Tank	L1	L1	
	Lake	19.9	3	

October 11, 2017	Sample Station #2 Earl Street near the school	L1	L1	
	Sample Station # 3 Marble Bay Road @ Van Anda Ave	L1	L1	
	Sample Station # 4 Smelter Road, across from Bob Gordon's	L1	L1	
	Sample Station # 5 Sellentin Street @ Sturt Bay Road	L1	L1	
	Sample Station # 6 Wall Street Pumphouse	L1	L1	
	Sample Station # 7 Copper Queen Street @ Alladin	L1	L1	
	Sample Station # 8 Storage Tank	L1	L1	
	Lake	547.5	1	

September 20, 2017	Sample Station #2 Earl Street near the school	L1	L1
	Sample Station # 3 Marble Bay Road @ Van Anda Ave	L1	L1
	Sample Station # 4 Smelter Road, across from Bob Gordon's	L1	L1
	Sample Station # 5 Sellentin Street @ Sturt Bay Road	L1	L1
	Sample Station # 6 Wall Street Pumphouse	L1	L1
	Sample Station # 7 Copper Queen Street @ Alladin	L1	L1
	Sample Station # 8 Storage Tank	L1	L1
	Lake	G2419.2	L1

<u>Date</u>	<u>Location</u>	<u>Total</u>	<u>Ecoli</u>	<u>Notes</u>
September 8, 2017	Sample Station #2 Earl Street near the school	L1	L1	
	Sample Station # 3 Marble Bay Road @ Van Anda Ave	OG	OG	
	Sample Station # 4 Smelter Road, across from Bob Gordon's	L1	L1	
	Sample Station # 5 Sellentin Street @ Sturt Bay Road	L1	L1	
	Sample Station # 6 Wall Street Pumphouse	L1	L1	
	Sample Station # 7 Copper Queen Street @ Alladin	OG	OG	
	Sample Station # 8 Storage Tank	L1	L1	
	Lake	G2419.2	L1	

<u>Date</u>	<u>Location</u>	<u>Total</u>	<u>Ecoli</u>	<u>Notes</u>
August 30, 2017	Sample Station #2 Earl Street near the school	L1	L1	
	Sample Station # 3 Marble Bay Road @ Van Anda Ave	L1	L1	
	Sample Station # 4 Smelter Road, across from Bob Gordon's	L1	L1	
	Sample Station # 5 Sellentin Street @ Sturt Bay Road	L1	L1	
	Sample Station # 6 Wall Street Pumphouse	L1	L1	
	Sample Station # 7 Copper Queen Street @ Alladin	L1	L1	
	Sample Station # 8 Storage Tank	L1	L1	
	Lake	G2419.2	2	

August 16, 2017	Sample Station #2 Earl Street near the school	L1	L1
	Sample Station # 3 Marble Bay Road @ Van Anda Ave	L1	L1
	Sample Station # 4 Smelter Road, across from Bob Gordon's	L1	L1
	Sample Station # 5 Sellentin Street @ Sturt Bay Road	L1	L1
	Sample Station # 6 Wall Street Pumphouse	L1	L1

	Sample Station # 7 Copper Queen Street @ Alladin	L1	L1
	Sample Station # 8 Storage Tank	L1	L1
	Lake	G2419.2	L1
August 8, 2017	Sample Station #2 Earl Street near the school	<b>Total</b>	L1
	Sample Station # 3 Marble Bay Road @ Van Anda Ave	L1	OG
	Sample Station # 4 Smelter Road, across from Bob Gordon's	OG	L1
	Sample Station # 5 Sellentin Street @ Sturt Bay Road	L1	L1
	Sample Station # 6 Wall Street Pumphouse	L1	L1
	Sample Station # 7 Copper Queen Street @ Alladin	L1	OG
	Sample Station # 8 Storage Tank	OG	L1
	Lake	L1	L1
		2419.2	
August 5, 2017			L1
	Sample Station #2 Earl Street near the school	L1	L1
	Sample Station # 3 Marble Bay Road @ Van Anda Ave	L1	L1
	Sample Station # 4 Smelter Road, across from Bob Gordon's	L1	L1
	Sample Station # 5 Sellentin Street @ Sturt Bay Road	L1	OG
	Sample Station # 6 Wall Street Pumphouse	OG	L1
	Sample Station # 7 Copper Queen Street @ Alladin	13	L1
	Sample Station # 8 Storage Tank	L1	L1
	Lake	2419.2	
July 19, 2017			L1
	Sample Station #2 Earl Street near the school	L1	L1
	Sample Station # 3 Marble Bay Road @ Van Anda Ave	880 Est	L1
	Sample Station # 4 Smelter Road, across from Bob Gordon's	L1	L1
	Sample Station # 5 Sellentin Street @ Sturt Bay Road	L1	L1
	Sample Station # 6 Wall Street Pumphouse	L1	L1
	Sample Station # 7 Copper Queen Street @ Alladin	L1	L1
	Sample Station # 8 Storage Tank	L1	L1
	Lake	2419.2	
July 5, 2017			L1
	Sample Station #2 Earl Street near the school	L1	L1

Sample Station # 3 Marble Bay Road @ Van Anda Ave	L1	L1
Sample Station # 4 Smelter Road, across from Bob Gordon's	L1	L1
Sample Station # 5 Sellentin Street @ Sturt Bay Road	L1	L1
Sample Station # 6 Wall Street Pumphouse	L1	L1
Sample Station # 7 Copper Queen Street @ Alladin	L1	L1
Sample Station # 8 Storage Tank	L1	7.4
Lake	238.2	

L 1 = less-than-one (1) or zero(0)

A = Sample not tested, too long in transit

EST = High colony density preventing accurate count

G = Greater than

O/G = Overgrown with coliform presnt

B = More than 200 background colonies / 100 ml

D = Sample not tested; no collection date given

T = Sample submitted exceeded 30 hours holding time

<u>Date</u>	<u>Location</u>	<u>Total</u>	<u>Ecoli</u>	<u>Notes</u>
July 4, 2017	Sample Station #2 Earl Street near the school	L1	L1	
	Sample Station # 3 Marble Bay Road @ Van Anda Ave	L1	L1	
	Sample Station # 4 Smelter Road, across from Bob Gordon's	L1	L1	
	Sample Station # 5 Sellentin Street @ Sturt Bay Road	L1	L1	
	Sample Station # 6 Wall Street Pumphouse	L1	L1	
	Sample Station # 7 Copper Queen Street @ Alladin	L1	L1	
	Sample Station # 8 Storage Tank	L1	L1	
	Lake	131.3		
June 27, 2017	Sample Station #2 Earl Street near the school	L1	L1	BOIL WATER REMAINS IN EFFECT
	Sample Station # 3 Marble Bay Road @ Van Anda Ave	L1	L1	
	Sample Station # 4 Smelter Road, across from Bob Gordon's	L1	L1	
	Sample Station # 5 Sellentin Street @ Sturt Bay Road	L1	L1	
	Sample Station # 6 Wall Street Pumphouse	L1	L1	
	Sample Station # 7 Copper Queen Street @ Alladin	L1	L1	
	Sample Station # 8 Storage Tank	L1	L1	
	Lake	133.4		
<u>Date</u>			<u>Ecoli</u>	

June 20, 2017	<b><u>Location</u></b>	<b><u>Total</u></b>	
	Sample Station #2 Earl Street near the school	10	L1
	Sample Station # 3 Marble Bay Road @ Van Anda Ave	5	OG
	Sample Station # 4 Smelter Road, across from Bob Gordon's	OG	L1
	Sample Station # 5 Sellentin Street @ Sturt Bay Road	200.5	L1
	Sample Station # 6 Wall Street Pumphouse	L1	L1
	Sample Station # 7 Copper Queen Street @ Alladin	5.3	L1
	Sample Station # 8 Storage Tank	34.4	

L 1 = less-than-one (1) or z Lake

A = Sample not tested, too long in transit

EST = High colony density preventing accurate count

G = Greater than

O/G = Overgrown with coliform presnt

B = More than 200 background colonies / 100 ml

D = Sample not tested; no collection date given

T = Sample submitted exceeded 30 hours holding time

**Date**

June 14, 2017	Sample Station # 4 Smelter Road, across from Bob Gordon's		OG
	Sample Station # 5 Sellentin Street @ Sturt Bay Road	OG	OG
	Sample Station # 6 Wall Street Pumphouse	OG	OG
	Sample Station # 7 Copper Queen Street @ Alladin	OG	OG
	Sample Station # 8 Storage Tank	OG	L1
	Lake	224.7	

May 31, 2017			L1
	Sample Station #2	L1	L1
	Sample Station # 3	L1	L1
	Sample Station # 4	L1	
	Sample Station # 5		
	Sample Station # 6		
	Sample Station # 7		
	Sample Station # 8		5.2
	Lake	172.2	

**Date**

May 25, 2017	<b><u>Location</u></b>	<b><u>Total</u></b>	<b><u>Ecoli</u></b>	<b><u>Notes</u></b>
	Sample Station #2	L1	L1	
	Sample Station # 3	L1	L1	
	Sample Station # 4	L1		

Sample Station # 5	
Sample Station # 6	
Sample Station # 7	
Sample Station # 8	5.2
Lake	172.2

L 1 = less-than-one (1) or zero(0)

A = Sample not tested, too long in transit

EST = High colony density preventing accurate count

G = Greater than

O/G = Overgrown with coliform present

B = More than 200 background colonies / 100 ml

D = Sample not tested; no collection date given

T = Sample submitted exceeded 30 hours holding time

**Date**

May 10, 2017

**Location**

Sample Station #2  
 Sample Station # 3  
 Sample Station # 4  
 Sample Station # 5  
 Sample Station # 6  
 Sample Station # 7  
 Sample Station # 8  
 Lake

**Total**

**Ecoli**

**Notes**

	L1
L1	L1
L1	L1
L1	L1
L1	L1
L1	L1
25	

**Date**

April 25, 2017

**Location**

Sample Station #2  
 Sample Station # 3  
 Sample Station # 4  
 Sample Station # 5  
 Sample Station # 6  
 Sample Station # 7  
 Sample Station # 8  
 Lake

**Total**

**Ecoli**

**Notes**

	L1
L1	L1
L1	L1
L1	
	L1
36.4	

**Date**

**Ecoli**

**Notes**

April 12, 2017

**Location**

- Sample Station #2
- Sample Station # 3
- Sample Station # 4
- Sample Station # 5
- Sample Station # 6
- Sample Station # 7
- Sample Station # 8

**Total**

- L1
- L1
- L1
- L1
- L1
- L1
- L1

6.3

L 1 = less-than-one (1) or z Lake

A = Sample not tested, too long in transit

EST = High colony density preventing accurate count

G = Greater than

O/G = Overgrown with coliform presnt

B = More than 200 background colonies / 100 ml

D = Sample not tested; no collection date given

T = Sample submitted exceeded 30 hours holding time

**Date**

April 1, 2017

**Location**

- Sample Station #2
- Sample Station # 3
- Sample Station # 4
- Sample Station # 5
- Sample Station # 6
- Sample Station # 7
- Sample Station # 8
- Lake

**Total**

- L1
- L1
- L1
- L1
- 
- 
- 

13.1

**Ecoli**

**Notes**

**Date**

March 15, 2017

**Location**

- Sample Station #2
- Sample Station # 3
- Sample Station # 4
- Sample Station # 5
- Sample Station # 6
- Sample Station # 7
- Sample Station # 8
- Lake

**Total**

- L1
- L1
- L1
- L1
- L1
- L1
- L1

8.6

**Ecoli**

**Notes**

**Date**

**Ecoli**

**Notes**

February 14, 2017

**Location**

Sample Station #2  
Sample Station # 3  
Sample Station # 4  
Sample Station # 5  
Sample Station # 6  
Sample Station # 7  
Sample Station # 8

**Total**

L1  
L1 L1  
L1 L1  
L1 L1  
L1 L1  
11

L 1 = less-than-one (1) or z Lake

A = Sample not tested, too long in transit

EST = High colony density preventing accurate count

G = Greater than

O/G = Overgrown with coliform presnt

B = More than 200 background colonies / 100 ml

D = Sample not tested; no collection date given

T = Sample submitted exceeded 30 hours holding time

Date

January 25, 2017

**Location**

Sample Station #2  
Sample Station # 3  
Sample Station # 4  
Sample Station # 5  
Sample Station # 6  
Sample Station # 7  
Sample Station # 8  
Lake

**Total**

L1  
L1 L1  
L1 L1  
L1  
L1  
L1  
12

**Ecoli**    **Notes**