

L 1 = less-than-one (1) or zero(0)

A = Sample not tested, too long in transit

EST = High colony density preventing accurate count

G = Greater than

O/G = Overgrown with coliform present

B = More than 200 background colonies / 100 ml

D = Sample not tested; no collection date given

T = Sample submitted exceeded 30 hours holding time

<u>Date</u>	<u>Location</u>	<u>Total coliform</u>	<u>Total E. Coli</u>
December 18, 2018	Sample Station # 1 Behind Hotel	L1	L1
	Sample Station #2 Earl Street near the school	L1	L1
	Sample Station # 3 Marble Bay Road @ Van Anda Ave	L1	L1
	Sample Station # 4 Smelter Road, across from Bob Gordon's	22	L1
	Sample Station # 5 Sellentin Street @ Sturt Bay Road	L1	L1
	Sample Station # 6 Wall Street Pumphouse	29	L1
	Sample Station # 7 Copper Queen Street @ Alladin	1	L1
	Sample Station # 8 Storage Tank Lake	L1 52.9	L1 L1
November 28, 2018	Sample Station # 1 Behind Hotel	L1	L1
	Sample Station #2 Earl Street near the school	L1	L1
	Sample Station # 3 Marble Bay Road @ Van Anda Ave	L1	L1
	Sample Station # 4 Smelter Road, across from Bob Gordon's	22	L1
	Sample Station # 5 Sellentin Street @ Sturt Bay Road	L1	L1
	Sample Station # 6 Wall Street Pumphouse	29	L1
	Sample Station # 7 Copper Queen Street @ Alladin	1	L1
	Sample Station # 8 Storage Tank Lake	L1	L1
October 2, 2018	Sample Station # 1 Behind Hotel	L1	L1
	Sample Station #2 Earl Street near the school	L1	L1
	Sample Station # 3 Marble Bay Road @ Van Anda Ave	L1	L1
	Sample Station # 4 Smelter Road, across from Bob Gordon's	22	L1
	Sample Station # 5 Sellentin Street @ Sturt Bay Road	L1	L1
	Sample Station # 6 Wall Street Pumphouse	29	L1
	Sample Station # 7 Copper Queen Street @ Alladin	1	L1

	Sample Station # 8 Storage Tank Lake	L1	L1
September 25, 2018	Sample Station # 1 Behind Hotel	L1	L1
	Sample Station #2 Earl Street near the school	L1	L1
	Sample Station # 3 Marble Bay Road @ Van Anda Ave	L1	L1
	Sample Station # 4 Smelter Road, across from Bob Gordon's	22	L1
	Sample Station # 5 Sellentin Street @ Sturt Bay Road	L1	L1
	Sample Station # 6 Wall Street Pumphouse	29	L1
	Sample Station # 7 Copper Queen Street @ Alladin	1	L1
	Sample Station # 8 Storage Tank	L1	L1
	Lake	2419.2	4.1
September 19, 2018	Sample Station # 1 Behind Hotel	L1	L1
	Sample Station #2 Earl Street near the school	L1	L1
	Sample Station # 3 Marble Bay Road @ Van Anda Ave	L1	L1
	Sample Station # 4 Smelter Road, across from Bob Gordon's	22	L1
	Sample Station # 5 Sellentin Street @ Sturt Bay Road	L1	L1
	Sample Station # 6 Wall Street Pumphouse	14	L1
	Sample Station # 7 Copper Queen Street @ Alladin	1	L1
	Sample Station # 8 Storage Tank	L1	L1
	Lake	2419.2	L1
August 22, 2018	Sample Station #2 Earl Street near the school	L1	L1
	Sample Station # 3 Marble Bay Road @ Van Anda Ave	L1	L1
	Sample Station # 4 Smelter Road, across from Bob Gordon's	L1	L1
	Sample Station # 5 Sellentin Street @ Sturt Bay Road	L1	L1
	Sample Station # 6 Wall Street Pumphouse	L1	L1
	Sample Station # 7 Copper Queen Street @ Alladin	1	L1
	Sample Station # 8 Storage Tank	L1	L1
	Lake	547.5	L1
July 21, 2018	Sample Station #2 Earl Street near the school	L1	L1
	Sample Station # 3 Marble Bay Road @ Van Anda Ave	2	L1

Sample Station # 4 Smelter Road, across from Bob Gordon's	L1	L1
Sample Station # 5 Sellentin Street @ Sturt Bay Road	L1	L1
Sample Station # 6 Wall Street Pumphouse	L1	L1
Sample Station # 7 Copper Queen Street @ Alladin	1	L1
Sample Station # 8 Storage Tank	L1	L1
Lake	1203.3	1

June 20, 2018

Sample Station #2 Earl Street near the school	L1	L1
Sample Station # 3 Marble Bay Road @ Van Anda Ave	L1	L1
Sample Station # 4 Smelter Road, across from Bob Gordon's	L1	L1
Sample Station # 5 Sellentin Street @ Sturt Bay Road	L1	L1
Sample Station # 6 Wall Street Pumphouse	L1	L1
Sample Station # 7 Copper Queen Street @ Alladin	L1	L1
Sample Station # 8 Storage Tank	L1	L1
Lake	547.5	L1

**Date**

**Location**

**Total**

**Ecoli**

**Notes**

May 16, 2018

Sample Station #2 Earl Street near the school	L1	L1
Sample Station # 3 Marble Bay Road @ Van Anda Ave	L1	L1
Sample Station # 4 Smelter Road, across from Bob Gordon's	L1	L1
Sample Station # 5 Sellentin Street @ Sturt Bay Road	L1	L1
Sample Station # 6 Wall Street Pumphouse	L1	L1
Sample Station # 7 Copper Queen Street @ Alladin	L1	L1
Sample Station # 8 Storage Tank	L1	L1
Lake	129.1	1

April 25, 2018

Sample Station #2 Earl Street near the school	L1	L1
Sample Station # 3 Marble Bay Road @ Van Anda Ave	L1	L1
Sample Station # 4 Smelter Road, across from Bob Gordon's	L1	L1
Sample Station # 5 Sellentin Street @ Sturt Bay Road	L1	L1
Sample Station # 6 Wall Street Pumphouse	L1	L1
Sample Station # 7 Copper Queen Street @ Alladin	L1	L1
Sample Station # 8 Storage Tank	L1	L1
Lake	104.6	1

March 31, 2018	Sample Station #2 Earl Street near the school	L1	L1
	Sample Station # 3 Marble Bay Road @ Van Anda Ave	L1	L1
	Sample Station # 4 Smelter Road, across from Bob Gordon's	L1	L1
	Sample Station # 5 Sellentin Street @ Sturt Bay Road	L1	L1
	Sample Station # 6 Wall Street Pumphouse	L1	L1
	Sample Station # 7 Copper Queen Street @ Alladin	L1	L1
	Sample Station # 8 Storage Tank	L1	L1
	Lake	14.5	1

<u>Date</u>	<u>Location</u>	<u>Total</u>	<u>Ecoli</u>	<u>Notes</u>
February 28, 2018	Sample Station #2 Earl Street near the school	L1	L1	
	Sample Station # 3 Marble Bay Road @ Van Anda Ave	L1	L1	
	Sample Station # 4 Smelter Road, across from Bob Gordon's	L1	L1	
	Sample Station # 5 Sellentin Street @ Sturt Bay Road	L1	L1	
	Sample Station # 6 Wall Street Pumphouse	L1	L1	
	Sample Station # 7 Copper Queen Street @ Alladin	L1	L1	
	Sample Station # 8 Storage Tank	L1	L1	
	Lake	18.9	1	

<u>Date</u>	<u>Location</u>	<u>Total</u>	<u>Ecoli</u>	<u>Notes</u>
February 17,2018	Sample Station #2 Earl Street near the school	L1	L1	
	Sample Station # 3 Marble Bay Road @ Van Anda Ave	L1	L1	
	Sample Station # 4 Smelter Road, across from Bob Gordon's	L1	L1	
	Sample Station # 5 Sellentin Street @ Sturt Bay Road	L1	L1	
	Sample Station # 6 Wall Street Pumphouse	L1	L1	
	Sample Station # 7 Copper Queen Street @ Alladin	L1	L1	
	Sample Station # 8 Storage Tank	L1	L1	
	Lake	28.1	L1	