

L 1 = less-than-one (1) or zero(0)

A = Sample not tested, too long in transit

EST = High colony density preventing accurate count

G = Greater than

O/G = Overgrown with coliform present

B = More than 200 background colonies / 100 ml

D = Sample not tested; no collection date given

T = Sample submitted exceeded 30 hours holding time

<u>Date</u>	<u>Location</u>	<u>Total coliform</u>	<u>Total</u>	<u>E. Coli</u>
17-Dec-19	Sample Station # 1 Behind Hotel	L1	L1	
	Sample Station #2 Earl Street near the school	L1	L1	
	Sample Station # 3 Marble Bay Road @ Van Anda Ave	L1	L1	
	Sample Station # 4 Smelter Road, across from Bob Gordon's	L1	L1	
	Sample Station # 5 Sellentin Street @ Sturt Bay Road	L1	L1	
	Sample Station # 6 Wall Street Pumphouse	L1	L1	
	Sample Station # 7 Copper Queen Street @ Alladin	L1	L1	
	Sample Station # 8 Storage Tank	L1	L1	
	Lake	29.8	2.0	
27-Nov-19	Sample Station # 1 Behind Hotel	L1	L1	
	Sample Station #2 Earl Street near the school	L1	L1	
	Sample Station # 3 Marble Bay Road @ Van Anda Ave	L1	L1	
	Sample Station # 4 Smelter Road, across from Bob Gordon's	L1	L1	
	Sample Station # 5 Sellentin Street @ Sturt Bay Road	L1	L1	
	Sample Station # 6 Wall Street Pumphouse	L1	L1	
	Sample Station # 7 Copper Queen Street @ Alladin	L1	L1	
	Sample Station # 8 Storage Tank	L1	L1	
	Lake	39.3	1.0	
23-Oct-19	Sample Station # 1 Behind Hotel	L1	L1	
	Sample Station #2 Earl Street near the school	L1	L1	
	Sample Station # 3 Marble Bay Road @ Van Anda Ave	L1	L1	
	Sample Station # 4 Smelter Road, across from Bob Gordon's	L1	L1	
	Sample Station # 5 Sellentin Street @ Sturt Bay Road	L1	L1	
	Sample Station # 6 Wall Street Pumphouse	L1	L1	
	Sample Station # 7 Copper Queen Street @ Alladin	L1	L1	
	Sample Station # 8 Storage Tank	L1	L1	
	Lake	224.9	L1	

2019-Sept-18	Sample Station # 1 Behind Hotel	L1	L1
	Sample Station #2 Earl Street near the school	L1	L1
	Sample Station # 3 Marble Bay Road @ Van Anda Ave	L1	L1
	Sample Station # 4 Smelter Road, across from Bob Gordon's	L1	L1
	Sample Station # 5 Sellentin Street @ Sturt Bay Road	L1	L1
	Sample Station # 6 Wall Street Pumphouse	L1	L1
	Sample Station # 7 Copper Queen Street @ Alladin	L1	L1
	Sample Station # 8 Storage Tank	L1	L1
	Lake	2419.2	1
	New Tank	L1	L1
2019-Aug-21	Sample Station # 1 Behind Hotel	L1	L1
	Sample Station #2 Earl Street near the school	L1	L1
	Sample Station # 3 Marble Bay Road @ Van Anda Ave	L1	L1
	Sample Station # 4 Smelter Road, across from Bob Gordon's	L1	L1
	Sample Station # 5 Sellentin Street @ Sturt Bay Road	L1	L1
	Sample Station # 6 Wall Street Pumphouse	L1	L1
	Sample Station # 7 Copper Queen Street @ Alladin	L1	L1
	Sample Station # 8 Storage Tank	L1	L1
	Lake	1299.7	L1
2019-Jul-24	Sample Station # 1 Behind Hotel	L1	L1
	Sample Station #2 Earl Street near the school	L1	L1
	Sample Station # 3 Marble Bay Road @ Van Anda Ave	L1	L1
	Sample Station # 4 Smelter Road, across from Bob Gordon's	L1	L1
	Sample Station # 5 Sellentin Street @ Sturt Bay Road	L1	L1
	Sample Station # 6 Wall Street Pumphouse	L1	L1
	Sample Station # 7 Copper Queen Street @ Alladin	L1	L1
	Sample Station # 8 Storage Tank	L1	L1
	Lake	501.2	1
29-Jun-19	Sample Station # 1 Behind Hotel	L1	L1

	Sample Station #2 Earl Street near the school	L1	L1
	Sample Station # 3 Marble Bay Road @ Van Anda Ave	L1	L1
	Sample Station # 4 Smelter Road, across from Bob Gordon's	L1	L1
	Sample Station # 5 Sellentin Street @ Sturt Bay Road	L1	L1
	Sample Station # 6 Wall Street Pumphouse	L1	L1
	Sample Station # 7 Copper Queen Street @ Alladin	L1	L1
	Sample Station # 8 Storage Tank	L1	L1
	Lake	1046.2	L1
May 29, 2019	Sample Station # 1 Behind Hotel	L1	L1
	Sample Station #2 Earl Street near the school	L1	L1
	Sample Station # 3 Marble Bay Road @ Van Anda Ave	L1	L1
	Sample Station # 4 Smelter Road, across from Bob Gordon's	L1	L1
	Sample Station # 5 Sellentin Street @ Sturt Bay Road	L1	L1
	Sample Station # 6 Wall Street Pumphouse	L1	L1
	Sample Station # 7 Copper Queen Street @ Alladin	L1	L1
	Sample Station # 8 Storage Tank	L1	L1
	Lake	613.1	1
April 30, 2019	Sample Station # 1 Behind Hotel	L1	L1
	Sample Station #2 Earl Street near the school	L1	L1
	Sample Station # 3 Marble Bay Road @ Van Anda Ave	L1	L1
	Sample Station # 4 Smelter Road, across from Bob Gordon's	L1	L1
	Sample Station # 5 Sellentin Street @ Sturt Bay Road	L1	L1
	Sample Station # 6 Wall Street Pumphouse	L1	L1
	Sample Station # 7 Copper Queen Street @ Alladin	L1	L1
	Sample Station # 8 Storage Tank	L1	L1
	Lake	344.8	1
March 30, 2019	Sample Station # 1 Behind Hotel	L1	L1
	Sample Station #2 Earl Street near the school	L1	L1
	Sample Station # 3 Marble Bay Road @ Van Anda Ave	L1	L1
	Sample Station # 4 Smelter Road, across from Bob Gordon's	L1	L1
	Sample Station # 5 Sellentin Street @ Sturt Bay Road	L1	L1

	Sample Station # 6 Wall Street Pumphouse	L1	L1
	Sample Station # 7 Copper Queen Street @ Alladin	L1	L1
	Sample Station # 8 Storage Tank	L1	L1
	Lake	31.3	L1
February 27, 2019	Sample Station # 1 Behind Hotel	L1	L1
	Sample Station #2 Earl Street near the school	L1	L1
	Sample Station # 3 Marble Bay Road @ Van Anda Ave	L1	L1
	Sample Station # 4 Smelter Road, across from Bob Gordon's	L1	L1
	Sample Station # 5 Sellentin Street @ Sturt Bay Road	L1	L1
	Sample Station # 6 Wall Street Pumphouse	L1	L1
	Sample Station # 7 Copper Queen Street @ Alladin	L1	L1
	Sample Station # 8 Storage Tank	L1	L1
	Lake	22.8	L1
January 23, 2019	Sample Station # 1 Behind Hotel	L1	L1
	Sample Station #2 Earl Street near the school	L1	L1
	Sample Station # 3 Marble Bay Road @ Van Anda Ave	L1	L1
	Sample Station # 4 Smelter Road, across from Bob Gordon's	L1	L1
	Sample Station # 5 Sellentin Street @ Sturt Bay Road	L1	L1
	Sample Station # 6 Wall Street Pumphouse	L1	L1
	Sample Station # 7 Copper Queen Street @ Alladin	L1	L1
	Sample Station # 8 Storage Tank	L1	L1
	Lake	70.8	L1

Notes

Notes

