

L 1 = less-than-one (1) or zero(0)

A = Sample not tested, too long in transit

EST = High colony density preventing accurate count

G = Greater than

O/G = Overgrown with coliform present

B = More than 200 background colonies / 100 ml

D = Sample not tested; no collection date given

T = Sample submitted exceeded 30 hours holding time

<b>Date</b>	<b>Location</b>	<b>Total coliform</b>	<b>Total E. Coli</b>
<b>27-Jan-20</b>	Sample Station # 1 Behind Hotel	L1	L1
	Sample Station #2 Earl Street near the school	L1	L1
	Sample Station # 3 Marble Bay Road @ Van Anda Ave	L1	L1
	Sample Station # 4 Smelter Road, across from Bob Gordon's	L1	L1
	Sample Station # 5 Sellentin Street @ Sturt Bay Road	L1	L1
	Sample Station # 6 Wall Street Pumphouse	L1	L1
	Sample Station # 7 Copper Queen Street @ Alladin	L1	L1
	Sample Station # 8 Storage Tank	L1	L1
	Lake	101.9	L1
<b>12-Feb-20</b>	Sample Station # 1 Behind Hotel	L1	L1
	Sample Station #2 Earl Street near the school	L1	L1
	Sample Station # 3 Marble Bay Road @ Van Anda Ave	L1	L1
	Sample Station # 4 Smelter Road, across from Bob Gordon's	L1	L1
	Sample Station # 5 Sellentin Street @ Sturt Bay Road	L1	L1
	Sample Station # 6 Wall Street Pumphouse	L1	L1
	Sample Station # 7 Copper Queen Street @ Alladin	L1	L1
	Sample Station # 8 Storage Tank	L1	L1
	Lake	52.0	3.0
<b>31-Mar-20</b>	Sample Station # 1 Behind Hotel	L1	L1
	Sample Station #2 Earl Street near the school	L1	L1
	Sample Station # 3 Marble Bay Road @ Van Anda Ave	L1	L1
	Sample Station # 4 Smelter Road, across from Bob Gordon's	L1	L1
	Sample Station # 5 Sellentin Street @ Sturt Bay Road	L1	L1
	Sample Station # 6 Wall Street Pumphouse	L1	L1
	Sample Station # 7 Copper Queen Street @ Alladin	L1	L1
	Sample Station # 8 Storage Tank	L1	L1
	Lake		





**Notes**

**Notes**

