

L 1 = less-than-one (1) or zero (0)

A = Sample not tested, too long in transit

EST = High colony density preventing accurate count

G = Greater than

O/G = Overgrown with coliform present

B = More than 200 background colonies / 100 ml

D = Sample not tested; no collection date given

T = Sample submitted exceeded 30 hours holding time

| Date | Location | Column1 | Total coliform | Total | E. Coli |
|------------------|---|----------------|-----------------------|--------------|----------------|
| 31-Mar-20 | Sample Station # 1 Behind Hotel | | L1 | | L1 |
| | Sample Station #2 Earl Street near the school | | L1 | | L1 |
| | Sample Station # 3 Marble Bay Road @ Van Anda Ave | | L1 | | L1 |
| | Sample Station # 4 Smelter Road, across from Bob Gordon's | | L1 | | L1 |
| | Sample Station # 5 Sellentin Street @ Sturt Bay Road | | L1 | | L1 |
| | Sample Station # 6 Wall Street Pumphouse | | L1 | | L1 |
| | Sample Station # 7 Copper Queen Street @ Alladin | | L1 | | L1 |
| | Sample Station # 8 Storage Tank | | L1 | | L1 |
| | Lake | | | | |
| | | | | | |
| 29-Apr-20 | Sample Station # 1 Behind Hotel | | L1 | | L1 |
| | Sample Station #2 Earl Street near the school | | L1 | | L1 |
| | Sample Station # 3 Marble Bay Road @ Van Anda Ave | | L1 | | L1 |
| | Sample Station # 4 Smelter Road, across from Bob Gordon's | | L1 | | L1 |
| | Sample Station # 5 Sellentin Street @ Sturt Bay Road | | L1 | | L1 |
| | Sample Station # 6 Wall Street Pumphouse | | L1 | | L1 |
| | Sample Station # 7 Copper Queen Street @ Alladin | | L1 | | L1 |
| | Sample Station # 8 Storage Tank | | L1 | | L1 |
| | Pre-treatment raw water | | 83.6 | | L1 |
| | | | | | |
| 27-May-20 | Sample Station # 1 Behind Hotel | | L1 | | L1 |
| | Sample Station #2 Earl Street near the school | | L1 | | L1 |
| | Sample Station # 3 Marble Bay Road @ Van Anda Ave | | L1 | | L1 |
| | Sample Station # 4 Smelter Road, across from Bob Gordon's | | L1 | | L1 |
| | Sample Station # 5 Sellentin Street @ Sturt Bay Road | | L1 | | L1 |
| | Sample Station # 6 Wall Street Pumphouse | | L1 | | L1 |
| | Sample Station # 7 Copper Queen Street @ Alladin | | L1 | | L1 |
| | Sample Station # 8 Storage Tank | | L1 | | L1 |
| | Pre-treatment raw water | | 55.6 | | L1 |