

Date	TOTAL Coliform or E. Coli	Sample Station 1 Behind Hotel	Sample Station 2 Earl Street near the school	Sample Station 3 Marble Bay Road @ Van Anda Ave	Sample Station 4 Smelter Road, across from Bob Gordon's	Sample Station 5 Sellentin Street @ Sturt Bay Road	Sample Station 6 Wall Street Pump house	Sample Station 7 Copper Queen Street @ Alladin	Sample Station 8 Storage Tank	Lake
2021 Jul 28	Coliform	L1	L1	L1	L1	L1	L1	L1	L1	866.4
	E. Coli	L1	L1	L1	L1	L1	L1	L1	L1	L1
2021 Aug 25	Coliform	L1	L1	L1	L1	L1	L1	L1	L1	1986.3
	E. Coli	L1	L1	L1	L1	L1	L1	L1	L1	L1
2021 Oct 06	Coliform	L1	L1	L1	L1	L1	L1	L1	L1	980.4
	E. Coli	L1	L1	L1	L1	L1	L1	L1	L1	L1

L 1 = less-than-one (1) or zero (0)

A = Sample not tested, too long in transit

EST = High colony density preventing accurate count

G = Greater than

O/G = Overgrown with coliform present

B = More than 200 background colonies / 100 ml

D = Sample not tested; no collection date given

T = Sample submitted exceeded 30 hours holding time

Water Test Results