

Date	For	Sample Station 1	Sample Station 2	Sample Station 3	Sample Station 4	Sample Station 5	Sample Station 6	Sample Station 7	Sample Station 8	Before Treatment
		Behind Hotel	Earl Street near the school	Marble Bay Road @ Van Anda Ave	Smelter Road, across from Bob Gordon's	Sellentint Street @ Sturt Bay Road	Wall Street Pump house	Copper Queen Street @ Alladin	Storage Tank	Lake
2022 Mar 02	Coliform	L1	L1	L1	L1	L1	L1	L1	L1	34.1
	E. Coli	L1	L1	L1	L1	L1	L1	L1	L1	L1
2022 Apr 27	Coliform	L1	L1	L1	L1	L1	L1	L1	L1	32.7
	E. Coli	L1	L1	L1	L1	L1	L1	L1	L1	L1
2022 Jun 08	Coliform	L1	L1	L1	L1	L1	L1	L1	L1	135.4
	E. Coli	L1	L1	L1	L1	L1	L1	L1	L1	L1

L 1 = less-than-one (1) or zero (0)

A = Sample not tested, too long in transit

EST = High colony density preventing accurate count

G = Greater than

O/G = Overgrown with coliform present

B = More than 200 background colonies / 100 ml

D = Sample not tested; no collection date given

T = Sample submitted exceeded 30 hours holding time

Water Test Results