

Date	For	Sample Station 1	Sample Station 2	Sample Station 3	Sample Station 4	Sample Station 5	Sample Station 6	Sample Station 7	Sample Station 8	Sample Station 9	Sample Station 10	Before Treatment
		Behind Hotel	Earl Street near the school	Marble Bay Road @ Van Anda Ave	5124 Blewett	Sellentin Street @ Sturt Bay Road	Wall Street Pump house	Copper Queen Street @ Alladin	Storage Tank Outlet	Wall St end hydrant	Marble Bay Rd @ Sellentin	Lake
2024 Mar 12	Coliform	L1	L1	L1	L1	L1	L1	L1	L1	L1	L1	33.6
	E. Coli	L1	L1	L1	L1	L1	L1	L1	L1	L1	L1	L1
2024 Apr 09	Coliform	L1	L1	L1	L1	L1	L1	L1	L1	L1	L1	23.3
	E. Coli	L1	L1	L1	L1	L1	L1	L1	L1	L1	L1	L1
2024 May 14	Coliform	L1	L1	L1	L1	L1	L1	L1	L1	L1	L1	34.0
	E. Coli	L1	L1	L1	L1	L1	L1	L1	L1	L1	L1	L1
2024 Jun 11	Coliform	L1	L1	L1	L1	L1	L1	L1	L1	L1	L1	74.9
	E. Coli	L1	L1	L1	L1	L1	L1	L1	L1	L1	L1	L1
2024 Jul 03	Coliform	L1	L1	L1	L1	L1	L1	L1	L1	L1	L1	85.7
	E. Coli	L1	L1	L1	L1	L1	L1	L1	L1	L1	L1	L1
2024 Jul 17	Coliform	L1	L1	L1	L1	L1	L1	L1	L1	L1	L1	160.7
	E. Coli	L1	L1	L1	L1	L1	L1	L1	L1	L1	L1	L1
2024 Aug 06	Coliform	L1	L1	L1	2.0	L1	L1	L1	L1	L1	L1	1413.6
	E. Coli	L1	L1	L1	L1	L1	L1	L1	L1	L1	L1	1.0
2024 Aug 12	Coliform	L1	L1	L1	L1	L1	L1	L1	L1	L1	L1	> 2419.6
	E. Coli	L1	L1	L1	L1	L1	L1	L1	L1	L1	L1	1.0

L 1 = less-than-one (1) or zero (0)

A = Sample not tested, too long in transit

EST = High colony density preventing accurate count

G = Greater than

O/G = Overgrown with coliform present

B = More than 200 background colonies / 100 ml

D = Sample not tested; no collection date given

T = Sample submitted exceeded 30 hours holding time

Water Test Results