

Date	For	Sample Station 1	Sample Station 2	Sample Station 3	Sample Station 4	Sample Station 5	Sample Station 6	Sample Station 7	Sample Station 8	Sample Station 9	Sample Station 10	Before Treatment
		Behind Hotel	Earl Street near the school	Marble Bay Road @ Van Anda Ave	5124 Blewett	Sellentin Street @ Sturt Bay Road	Wall Street Pump house	Copper Queen Street @ Alladin	Storage Tank	Wall St end hydrant	Marble Bay Rd @ Sellentin	Lake
2023 Aug 01	Coliform	L1	L1	L1	L1	L1	L1	L1	L1	L1	L1	193.5
	E. Coli	L1	L1	L1	L1	L1	L1	L1	L1	L1	L1	L1
2023 Sep 06	Coliform	L1	L1	L1	L1	L1	L1	L1	L1	L1	L1	1119.9
	E. Coli	L1	L1	L1	L1	L1	L1	L1	L1	L1	L1	2.0
2023 Oct 03	Coliform	L1	L1	L1	L1	L1	L1	L1	L1	L1	L1	275.5
	E. Coli	L1	L1	L1	L1	L1	L1	L1	L1	L1	L1	6.3
2023 Nov 01	Coliform	L1	L1	L1	L1	L1	L1	L1	L1	L1	L1	69.7
	E. Coli	L1	L1	L1	L1	L1	L1	L1	L1	L1	L1	L1
2023 Dec 05	Coliform	L1	L1	L1	L1	L1	L1	L1	L1	L1	L1	62.0
	E. Coli	L1	L1	L1	L1	L1	L1	L1	L1	L1	L1	1.0
2024 Jan 08	Coliform	L1	L1	L1	L1	L1	L1	L1	L1	L1	L1	53.8
	E. Coli	L1	L1	L1	L1	L1	L1	L1	L1	L1	L1	1.0
2024 Jan 31	Coliform	L1	L1	L1	L1	L1	L1	L1	L1	L1	L1	88.4
	E. Coli	L1	L1	L1	L1	L1	L1	L1	L1	L1	L1	6.3

L 1 = less-than-one (1) or zero (0)

A = Sample not tested, too long in transit

EST = High colony density preventing accurate count

G = Greater than

O/G = Overgrown with coliform present

B = More than 200 background colonies / 100 ml

D = Sample not tested; no collection date given

T = Sample submitted exceeded 30 hours holding time

Water Test Results