

Date	For	Sample Station 1	Sample Station 2	Sample Station 3	Sample Station 4	Sample Station 5	Sample Station 6	Sample Station 7	Sample Station 8	Before Treatment
		Behind Hotel	Earl Street near the school	Marble Bay Road @ Van Anda Ave	Smelter Road, across from Bob Gordon's	Sellentint Street @ Sturt Bay Road	Wall Street Pump house	Copper Queen Street @ Alladin	Storage Tank	Lake
2022 Nov 02	Coliform	L1	L1	L1	L1	L1	L1	L1	L1	261.3
	E. Coli	L1	L1	L1	L1	L1	L1	L1	L1	L1
2022 Dec 07	Coliform	L1	L1	L1	L1	L1	L1	L1	L1	8.6
	E. Coli	L1	L1	L1	L1	L1	L1	L1	L1	L1
2023 Jan 04	Coliform	L1	L1	L1	L1	L1	L1	L1	L1	344.8
	E. Coli	L1	L1	L1	L1	L1	L1	L1	L1	9.7
2023 Feb 04	Coliform	L1	L1	L1	L1	L1	L1	L1	L1	24.6
	E. Coli	L1	L1	L1	L1	L1	L1	L1	L1	L1
2023 Mar 01	Coliform	L1	L1	L1	L1	L1	L1	L1	L1	13.2
	E. Coli	L1	L1	L1	L1	L1	L1	L1	L1	L1

L 1 = less-than-one (1) or zero (0)

A = Sample not tested, too long in transit

EST = High colony density preventing accurate count

G = Greater than

O/G = Overgrown with coliform present

B = More than 200 background colonies / 100 ml

D = Sample not tested; no collection date given

T = Sample submitted exceeded 30 hours holding time

Water Test Results