

Date	For	Sample Station 1	Sample Station 2	Sample Station 3	Sample Station 4	Sample Station 5	Sample Station 6	Sample Station 7	Sample Station 8	Sample Station 9	Sample Station 10	Before Treatment
		Behind Hotel	Earl Street near the school	Marble Bay Road @ Van Anda Ave	5124 Blewett	Sellentin Street @ Sturt Bay Road	Wall Street Pump house	Copper Queen Street @ Alladin	Storage Tank Outlet	Wall St end hydrant	Marble Bay Rd @ Sellentin	Lake
2024 Jul 17	Coliform	LT1	LT1	LT1	LT1	LT1	LT1	LT1	LT1	LT1	LT1	160.7
	E. Coli	LT1	LT1	LT1	LT1	LT1	LT1	LT1	LT1	LT1	LT1	LT1
2024 Aug 06	Coliform	LT1	LT1	LT1	2.0	LT1	LT1	LT1	LT1	LT1	LT1	1413.6
	E. Coli	LT1	LT1	LT1	LT1	LT1	LT1	LT1	LT1	LT1	LT1	1.0
2024 Aug 12	Coliform	LT1	LT1	LT1	LT1	LT1	LT1	LT1	LT1	LT1	LT1	G 2419.6
	E. Coli	LT1	LT1	LT1	LT1	LT1	LT1	LT1	LT1	LT1	LT1	1.0
2024 Aug 21	Coliform	LT1	LT1	LT1	LT1	LT1	LT1	LT1	LT1	LT1	LT1	G 2419.6
	E. Coli	LT1	LT1	LT1	LT1	LT1	LT1	LT1	LT1	LT1	LT1	3.1
2024 Sep 04	Coliform	LT1	LT1	6.0	LT1	12.0	LT1	LT1	LT1	LT1	LT1	517.2
	E. Coli	LT1	LT1	LT1	LT1	LT1	LT1	LT1	LT1	LT1	LT1	LT1
2024 Sep 17	Coliform	LT1	5.0	1.0	LT1	LT1	LT1	LT1	LT1	LT1 GTR200	LT1	209.8
	E. Coli	LT1	LT1	LT1	LT1	LT1	LT1	LT1	LT1	LT1 GTR200	LT1	1.0
2024 Sep 25	Coliform	LT1	LT1	LT1	LT1	LT1	LT1	LT1	LT1	LT1 GTR200	LT1	78.9
	E. Coli	LT1	LT1	LT1	LT1	LT1	LT1	LT1	LT1	LT1 GTR200	LT1	1.0
2024 Oct 02	Coliform	LT1	LT1	LT1	LT1	LT1	LT1	LT1	LT1	LT1	LT1	60.9
	E. Coli	LT1	LT1	LT1	LT1	LT1	LT1	LT1	LT1	LT1	LT1	1.0

# Water Test Results

LT 1 = less-than-one (1) or zero (0)

A = Sample not tested, too long in transit

EST = High colony density preventing accurate count

G = Greater than

O/G = Overgrown with coliform present

B = More than 200 background colonies / 100 ml

D = Sample not tested; no collection date given

T = Sample submitted exceeded 30 hours holding time

LT1 GTR200 = something growing that's not Coliforms or E. coli. Usually low risk.