

Date	For	Sample Station 1	Sample Station 2	Sample Station 3	Sample Station 4	Sample Station 5	Sample Station 6	Sample Station 7	Sample Station 8	Sample Station 9	Sample Station 10	Before Treatment
		Behind Hotel	Earl Street near the school	Marble Bay Road @ Van Anda Ave	5124 Blewett	Sellentin Street @ Sturt Bay Road	Wall Street Pump house	Copper Queen Street @ Alladin	Storage Tank	Wall St end hydrant	Marble Bay Rd @ Sellentin	Lake
2023 May 01	Coliform	L1	L1	L1	L1	L1	L1	L1	L1	L1	L1	53.7
	E. Coli	L1	L1	L1	L1	L1	L1	L1	L1	L1	L1	1.0
2023 May 31	Coliform	L1	L1	L1	L1	L1	L1	L1	L1	L1	L1	159.7
	E. Coli	L1	L1	L1	L1	L1	L1	L1	L1	L1	L1	2.0
2023 Jul 04	Coliform	L1	L1	L1	L1	L1	L1	L1	L1	L1	L1	111.2
	E. Coli	L1	L1	L1	L1	L1	L1	L1	L1	L1	L1	1.0
2023 Aug 01	Coliform	L1	L1	L1	L1	L1	L1	L1	L1	L1	L1	193.5
	E. Coli	L1	L1	L1	L1	L1	L1	L1	L1	L1	L1	0.0
2023 Sep 06	Coliform	L1	L1	L1	L1	L1	L1	L1	L1	L1	L1	1119.9
	E. Coli	L1	L1	L1	L1	L1	L1	L1	L1	L1	L1	2.0

L 1 = less-than-one (1) or zero (0)

A = Sample not tested, too long in transit

EST = High colony density preventing accurate count

G = Greater than

O/G = Overgrown with coliform present

B = More than 200 background colonies / 100 ml

D = Sample not tested; no collection date given

T = Sample submitted exceeded 30 hours holding time

# Water Test Results